

Certificate of Compliance

Certificate Number:

EX29727

Report Reference:

EX29727-20250819

Issue Date:

2025-August-19

Issued to:

VALVESEAL, S.L.
Ronda De Maiols 1
Bmc Building 3rd Floor Office 328
Sant Quirze Del Valles, 08192
ES

This certificate confirms that representative samples of:

BUTTERFLY VALVES

See addendum page for Model/Product

Has been evaluated by UL LLC in accordance with Standard(s) for Safety:

UL/ULC 1091 - Butterfly Valves for Fire-Protection Service


Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Owner

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.



Certificate of Compliance

Certificate Number: EX29727
Report Reference: EX29727-20250819
Issue Date: 2025-August-19

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Models.

Butterfly Valve

TF-BFV-G-UF, TF-BFV-W-UF, TF-BFV-HG-U, TF-BFV-HG-175U, TF-BFV-HFG-U, TF-BFV-HFG-175U